Part Number Update

Bulletin No: PNU-187-000

Effective Date: January 23, 2014

Cancels: NA

Subject: Bendix Announces Forward Looking Radar (FLR) Sensor Service Kit Part Numbers for Navistar® ProStar® Vehicles

Bendix announces that effective January 1, 2014, the Bendix[™] FLR20[™] radar sensor will be used as a replacement for Navistar[®] ProStar[®] vehicles originally equipped with the Bendix[™] FLR10[™] radar sensors. There are two kits, dependent on the build date of the vehicle.

Kits include the bracket and components needed to perform the installation, however an alignment tool (see below) and digital inclinometer will also be required to complete the installation and alignment.



Page: 1 of 2

Bendix™ FLR10™ Radar Sensors	For Navistar® ProStar® vehicles built 1/31/2011 and before	For Navistar® ProStar® vehicles built after 1/31/2011
(Core Class F6, Core Group SG)	(Core Class F8, Core Group SH)	
K043225	K097917 K097916	
K050056		
K050057		
K051511		
K056476		
K056480		K007016
K056481		K097916
K067883		
K067884		
K070393		
K090770		
K090778		

ALIGNMENT TOOLS

Bendix [®] Wingman [®] Alignment Tools		A Steel Clip <u>is also Required</u> for the Bendix FLR20 Radar Sensor Alignment Procedure
K041451	Bendy	
OR	Bridge Climanus	K073087
K065284	1	

Reference Document:


For more information about the radar sensor (including the alignment procedure), see the Bendix[®] Wingman[®] Advanced[™] (FLR20[™] sensor) Service Data Sheet: SD-61-4960. This document is available for download from the Bendix Document Library at www.bendix.com, or may be ordered from the Marketing Center.

Note: Return Bendix FLR10 radar sensors for Core credit. (See page 2 for Core return information).

Cancels: NA

CORE EXCHANGES

Since the Bendix™ FLR20™ radar sensor replaces a Bendix™ FLR10™ radar sensor, when customers return the part for Core credit it is important to use a BW1829 orange tag. This will alert the plant that the Core is eligible to be applied to the Bendix FLR20™ radar sensor Core group.



For more information about the change detailed in this document, please contact your Bendix Account Manager or Plant at 1-800-AIR-BRAKE (1-800-247-2725).

Log-on and Learn from the Best

On-line training that's available when you are -24/7/365. Visit www.brake-school.com.

